


Figure 3-7

Removal Process for BD/DR Projects



NOTE: CERCLA is not applicable to BD/DR projects unless those projects involve hazardous substances. Accordingly, the EE/CA process outlined in the NCP is not required.

Created By: JFL	Issue No.:0	Revision No.:0
Approved By: JC	Chapter 3- Figure 3-7	Date: 30 September 1999